Informal Interpretation Report
Number 7392

Date November 24, 2026

Edition 2010

Section 1015

Question:

Is it the intent of Section 1015.1 second Exception (inset) to prevent the removal of a 2nd exit door in an existing R-2 occupancy if that dwelling unit is not equipped throughout with an automatic sprinkler system in accordance with Section 903.3.1.1 or 903.3.1.2.

Notice:
The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.