Informal Interpretation Report
Number 8035

Date November 28, 2017

Edition 2014

Section C402.4.5.2

Question:

Section C402.4.5.2 has exceptions to the use of Class 1A motorized dampers. Exception 1 has subheadings for the exception. Does each subheading, (e.g. 1.4), stand by itself as an individual exception? or should all subheadings be taken together, (e.g. 1.1-1.4)?

Answer

They must be taken as a group. All apply to use the exception.

Commentary:

None

Notice:
The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.