Informal Interpretation Report
Number 8517

Date November 24, 2026

Edition 2007

Section 112.1

Question:

Is it the intent of art 112.1 to require a utility disconnect at the delivery point " weather head" to remove and or relocate existing service wiring on the load side of meter socket?

Notice:
The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.