

Owens Corning does not recommend the weaving of underlayment in the valley. Weaving underlayment in the valley can create air pockets that can lead to the underlayment bridging across the valley. Bridging underlayment can cause the shingles to lift, or buckle. If shingles lift or buckle due to bridging underlayment, this is not considered a manufacturing defect and therefore would not be covered under the Standard Product Limited Warranty for Roofing Shingles.

