



**Informal Interpretation Report
Number 6895**



Date January 24, 2012

Edition 2007

Section 10.24

Question:

Is it the intent of Exception 1 to allow 50% of the number and capacity of the exit enclosures to exit through a building (business occupancy) lobby and its adjoining exterior vestibule (for climate control conditions only)?

Answer

yes; if the vestibule described is a part of the lobby.

Commentary:

The answer refers to section 1024 not 10.24.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.