



**Informal Interpretation Report
Number 7586**



Date August 20, 2015

Edition 2010

Section 306.5.1

Question:

Is it the intent of this code to require TWO platforms, on each side of the appliance, and TWO guardrails, extending 30" beyond each end of the equipment, such as a rooftop restaurant exhaust fan on a sloped roof ?

Answer

Maybe. It would depend on where access is required to service the equipment.

Commentary:

None

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.