



**Informal Interpretation Report
Number 8337**



Date November 20, 2019

Edition 2017

Section 110.8.1

Question:

Is it the intent of section 110.8.1 to require a (Threshold) Special Inspector to perform the required inspections of structural repairs that are intended to restore an existing building to the original design condition? There are no modifications, changes, additions or alterations to the structural system or structural loading of the building being proposed.

Answer

The answer is no if the repairs described in the Comments are nonstructural assuming the building is a threshold building. The answer is yes for items that are structural such as the cracks if occurring in structural elements or the replacement of corroded rebar,

Commentary:

None.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.