



**Informal Interpretation Report
Number 7712**



Date 12/22/2015
Report 7712
Edition: 2014
Section Table 302.1(1)

Question:

Is it the intent of Table 302.1(1) to not allow glass block with a 1 hour rating in a wall built on a zero lot line? If the structures are separated by eight (8) would it be acceptable?

Answer:

No. Glass block is considered masonry and should be considered the same as other masonry units within a wall. The definition of masonry includes glass block and it is not considered an opening.

On 02/01/2016 at 10:58 AM

Commentary:

None

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Community Affairs, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.