

Informal Interpretation Report Number 5330



Date September 19, 2007

Edition 2004

Section 1009.11.1

Question:

Is it the intent of the FBC section 1009.11.1 to allow as an exception, handrails to form part of a guardrail at 42" high for an exterior staircase of an R2 (condo) upper level.

Answer

Yes, you can have the 42� handrail / guardrail if ALL the requirements of the exception are met. Example: If the stairs are not required to be accessible, because there are elevators or ramps providing vertical accessibility to the level(s)

Commentary:

This is not a reference or interpretation of Chapter 11 of the Florida Building Code. The question and response reference Chapter 10 and infer interpretation of only Chapter 10.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.