



**Informal Interpretation Report
Number 6861**



Date December 01, 2011

Edition 2007

Section 1009.3

Question:

Is it the intent of the code to measure stair tread width from inside of stringer to inside of stringer?

Answer

No. See Informal Interpretation Report Number 6435. The section quoted does not address the width of stairs it addresses the tread and riser dimensions.

Commentary:

None.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.