



**Informal Interpretation Report
Number 7156**



Date April 08, 2013

Edition 2010

Section R311.3.1

Question:

Is it the intent of R311.3.1 Exception That the door cannot swing over the landing or floor if the landing or floor is more than 1 1/2 inches below the threshold for the required egress door when other exterior doors allow 7 3/4 inches below threshold?

Answer

Yes, if this an egress door. If the door in question is not an egress door, R311.3.2 would apply.

Commentary:

None.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.