



**Informal Interpretation Report
Number 7464**



Date April 03, 2015

Edition 2007

Section 505.2.2

Question:

Is it the intent of Section 505.2.2 of the 2010 FBC-Energy Conservation to require automatic lighting control devices for an interior remodel of an an existing tenant space less than 5,000 sq ft?

Answer

Yes

Commentary:

If the alteration is a Level 2 Alteration, Per the Existing Building Code, Section 711.1, compliance with the Energy Code for all new Work is mandated.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.