



**Informal Interpretation Report
Number 7992**



Date September 19, 2017

Edition 2014

Section R403.2.2.1

Question:

Does the requirement of R403.2.2.1 for an air handler to have less than 2% air leakage apply when the air handler and ducts are located entirely within the building thermal envelope?

Answer

No

Commentary:

None

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.