



**Informal Interpretation Report
Number 8155**



Date August 20, 2018

Edition 2017

Section 3007.6.4

Question:

Is it the intent of section 3007.6.4 that if an enclosed fire service access elevator lobby is provided at the level of exit discharge it must meet the minimum size requirement of 150 square feet

Answer

Yes, Although, Section 3007.6.2 gives an exception where enclosed FSAE lobby would not be required at the levels of exit discharge, if an enclosure is built - it needs to meet the requirements of 3007.6.4. The ICC commentary states that the size needs to be adequate for conducting necessary fire fighter operations. It states most teams are composed of 3-4 fire fighters. Therefore the size.

Commentary:

None.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.