

Informal Interpretation Report Number 8340



Constant of the last of the la		

Date November 20, 2019

Edition 2017

Section 603

Question:

Is mechanical equipment (such as a fan coil unit) allowed in attics of Type I and II construction so long as it meets the requirements of 718.5? This is assuming the attic is designed as a 1-hour roof/ceiling assembly.

Answer

No. Clarifying - Wrong code book.

If this is a commercial building, Section C403.2.9.6 in the FBC-EC does not allow air handling units in attics of commercial buildings.

Section 603.1.1 has allowances for nonmetallic ducts installed per the FBC-Mech.

Commentary:

N	on	e.

Notice:

The Building Officials Association of Florida, in cooperation with the Florida Building Commission, the Florida Department of Business & Professional Regulation, ICC, and industry and professional experts offer this interpretation of the Florida Building Code in the interest of consistency in their application statewide. This interpretation is informal, non-binding and subject to acceptance and approval by the local building official.